#### **GILA RIVER BASIN**

### 09488600 SILVER REEF WASH NEAR CASA GRANDE, AZ

LOCATION.--Lat 32°40′56″, long 111°50′03″, SW¹/<sub>4</sub>SE¹/<sub>4</sub> sec.34, T.8 S., R.5 E., Pinal County, Hydrologic Unit 15050306, at Quijotoa-Casa Grande Road, 14 mi southwest of Casa Grande. DRAINAGE AREA.--12.8 mi².

## Annual peak discharges

| Water<br>year | Date     | Annual peak<br>discharge<br>(ft <sup>3</sup> /s) | Discharge codes | Water<br>year | Date     | Annual peak<br>discharge<br>(ft <sup>3</sup> /s) | Discharge<br>codes |
|---------------|----------|--|-----------------|---------------|----------|--|--------------------|
| 1950          | 00-00-50 | (1)  | HP              | 1969          | 08-11-69 | 165  |                    |
| 1963          | 08-21-63 | 662  |                 | 1970          | 00-00-70 | 630  |                    |
| 1964          | 08-12-64 | 1,170  |                 | 1971          | 08-03-71 | 1,400  |                    |
| 1965          | 09-00-65 | 100  | ES              | 1972          | 08-12-72 | 90   |                    |
| 1966          | 12-00-65 | 600  |                 | 1973          | 00-00-73 | 100  | ES                 |
| 1967          | 00-00-67 | 135  |                 | 1974          | 09-00-74 | 60   |                    |
| 1968          | 12-19-67 | 490  |                 | 1975          | 10-28-74 | 160  |                    |

<sup>&</sup>lt;sup>1</sup>Discharge unknown.

Magnitude and probability of instantaneous peak flow based on period of record 1963-75

| Discharge, in ft <sup>3</sup> /s, for indicated recurrence interval<br>in years, and exceedance probablility, in percent |          |           |          |           |            |  |
|--|----------|-----------|----------|-----------|------------|--|
| 2<br>50%   | 5<br>20% | 10<br>10% | 25<br>4% | 50†<br>2% | 100†<br>1% |  |
| 268  | 663      | 1,070     | 1,780    | 2,480     | 3,340      |  |
| Weighted skew  | (logs) = | 0.03      |          |           |            |  |
| Mean   | (logs) = | 2.43      |          |           |            |  |
| Standard dev.  | (logs) = | 0.47      |          |           |            |  |

<sup>†</sup> Reliability of values in column is uncertain, and potential errors are large.

### Basin characteristics

|                                     |                          |                                    |                               |               |   | Rainfall intensity, 24-hour |                 |
|-------------------------------------|--------------------------|------------------------------------|-------------------------------|---------------|---|-----------------------------|-----------------|
| Main<br>channel<br>slope<br>(ft/mi) | Stream<br>length<br>(mi) | Mean<br>basin<br>elevation<br>(ft) | Forested<br>area<br>(percent) | Soil<br>index | Mean<br>annual<br>precipitation<br>(in) | 2-year<br>(in)              | 50-year<br>(in) |
| 67.4                                | 8.6                      | 1,620                              | 0.0                           | 3.0           | 8.5                                     | 1.6                         | 4.1             |

# **GILA RIVER BASIN**

09488600 SILVER REEF WASH NEAR CASA GRANDE, AZ--Continued

